

Description of Works and date	Date of Faculty or Archdeacon's Certificate	Reference to Quinquennial Inspection Report	Contractor	Cost of Works including fees	Details of grant aid, from charitable trusts and other bodies	Whereabouts of specifications and drawings if not filed in the Log Book
Repairs decorate door. D.1. 6 June '96	-	1995 2.01.	G. Freeman	£85.05	-	-
Stonework repairs to the main door, 20 August 1996			Westcountry Stonemasons Ltd.	927.08	-	-
Installation of sound reinforcement and loop system.	Faculty, 4 Nov. 96		Keith Monks Sound Systems	2,083.92	-	
Restoration of Copper "Tail Feather" to weathercock August 1998			Robbie Saville Yealmbridge Forge	£85-		Photographs held in album
Completion of Cupboard for Securing Sound System				nil		None
Repair of locks to 2 wooden Donation boxes				nil		None

Description of Works and date	Date of Faculty or Archdeacon's Certificate	Reference to Quinquennial Inspection Report	Contractor	Cost of Works including fees	Details of grant aid, from charitable trusts and other bodies	Whereabouts of specifications and drawings if not filed in the Log Book
Replacement of Rusty high fittings September 1998		1990 Report 10. (A) page 4	FW Jarvis Kingston	£1245 + VAT		✓
Restoration of Oak Gates - Autumn 1998				nil		None
Painting of Metal Arch over Gates - March 1999 (installed 1997 1996)				nil		None
Replacement of Boiler Flue Cover 26 August 1998			M.B.R. Heat Systems	Treasurer's Records		None
Unblocking Down Pipes on North wall March 1999						None
Remedial work to Organ June 1999			Hale & Company Ltd	£736 + VAT		✓
Following trial period Communion Table moved forward August 1999.	Archdeacon's Approval			nil		None.

Description of Works and date	Date of Faculty or Archdeacon's Certificate	Reference to Quinquennial Inspection Report	Contractor	Cost of Works including fees	Details of grant aid, from charitable trusts and other bodies	Whereabouts of specifications and drawings if not filed in the Log Book
Repair to Donation Box after robbery August 1999				nil		none
Restoration of drain at bottom of down pipes on north wall. November 1999			George Freeman	Treasurer's records approx. £200		none
Broken Door Handle re-welded March 2000			The Forge Churchston	£3.50		none
Re-location of 31 Leadstones	11.1.00		Dave Yeoman	£750		✓
Repair of donations box damaged following forced entry. Oct 2000			(Parishioner)	NIL		
Provision of free-standing notice board in the church for leaflets / notices	June 2001 Schedule B		-	NIL (Gift)		
Temporary repair to historic glass in side chapel Nov. 2001				NIL		

Description of Works and date	Date of Faculty or Archdeacon's Certificate	Reference to Quinquennial Inspection Report	Contractor	Cost of Works including fees	Details of grant aid, from charitable trusts and other bodies	Whereabouts of specifications and drawings if not filed in the Log Book
Provision of fine wire mesh to prevent birds nesting inside bell tower. Nov 2001			George Freeman	£25 approx.		
Provision of more sensitive microphones to the lectern and overhaul of sound system. May 2002			Keith Marks.	£570+		
Renovation of porch noticeboard July 2002			Michael Tagent	(voluntary)		
Repair of step in Lady Chapel May 2003	Minor repair under Sch A			TBA		
Repair to South Chancel roof and east gable end. Removal and replacement of rotten rafter. Replacement of roof tiles augmented with reclaimed tiles Nov/Dec 2003	Sch B authorisation (entered) as emergency		South Hams Roofing (under guidance of Architect Andrew Wash)	TBA	Ecological £250	Sainsbury Trust £3500
Repairs to door furniture & flagpole	minor under Sch A		Phil Grett / Mar McCarty	voluntary		

Description of Works and date	Date of Faculty or Archdeacon's Certificate	Reference to Quinquennial Inspection Report	Contractor	Cost of Works including fees	Details of grant aid, from charitable trusts and other bodies	Whereabouts of specifications and drawings if not filed in the Log Book
<u>OCT 2003</u> Wall painting, report received			McNeilage conservation Exeter			2 DRAWER CHEST IN VESTRY.
<u>MAY 2007.</u> Sundial repaired			McNeilage conservation Exeter	£2526.25	Various donations	2 DR CHEST VESTRY
<u>MAY 2008</u> Organ overhaul Quotation rec'd.			Midland Organ, Hele + Co	£5,975 + VAT.	Not proceeded with	2 DRAWER CHEST IN VESTRY.
<u>JAN 2009.</u> New External Notice board manufactured & fitted to outside wall, R.H. side of gate.			Manufactured & donated by Alan McCarthy Ringmore	NIL	Village donated.	—

Description of Works and date	Date of Faculty or Archdeacon's Certificate	Reference to Quinquennial Inspection Report	Contractor	Cost of Works including fees	Details of grant aid, from charitable trusts and other bodies	Whereabouts of specifications and drawings if not filed in the Log Book
<p><u>JAN 2009:</u> Hymnal purchased to supplement organ when no organist available MODEL HT300 SERIAL No 3000500557</p> <p><u>JAN 2009:</u> CHURCH CLOCK STOPPED. CONTROL UNIT SENT BACK TO ENGLISH CLOCKMAKERS DERBYSHIRE FOR REPAIR. NOTE. UNIT FAILED DUE TO WATER INGRESS INTO IT. NEW CONTROL UNIT REQ'D PAID FOR BY RINGROSE PARISH COUNCIL.</p>			<p>HYMN TECHNOLOGY SURBITON KTI 96Q.</p> <p>ENGLISH CLOCKMAKERS DERBYSHIRE</p>	<p>£2,297.00 inc VAT</p>		<p>2 DRAWER CHEST IN VESTRY</p>

Description of Works and date	Date of Faculty or Archdeacon's Certificate	Reference to Quinquennial Inspection Report	Contractor	Cost of Works including fees	Details of grant aid, from charitable trusts and other bodies	Whereabouts of specifications and drawings if not filed in the Log Book
<p><u>JULY 2009</u> NEW CHURCH CLOCK CONTROL SUPPLIED</p> <p>ELECTRICAL ENGINEERS FITTED WEATHER PROOF BOX & INSTALLED CLOCK CONTROL UNIT WITHIN IT.</p> <p>ALSO WIRED IN HYMNAL UNIT, CONTROL BOX & LOUDSPEAKER</p>			<p>ENGLISH CLOCK MAKERS BERKSHIRE</p> <p>JARVIS & SON KINGSTON DEVON</p>	<p>CLOCK REPAIR PAID FOR BY RINGMORE PARISH COUNCIL</p>		
<p><u>JULY 2011</u> EXTERNAL CHURCH DOOR (2) REPRINTED</p>				<p>TIME & MATERIALS DONATED BY MIKE WILSON RINGMORE</p>		
<p><u>SEPTEMBER 2011</u> NEW CAST IRON CUTTING TOP OF MAIN DOOR DAMAGED IN HIGH WINDS & REPLACED TOGETHER WITH FIXINGS</p>			<p>AM KING & SONS RINGMORE</p>	<p>£ 356.12 + VAT</p>		

Description of Works and date	Date of Faculty or Archdeacon's Certificate	Reference to Quinquennial Inspection Report	Contractor	Cost of Works including fees	Details of grant aid, from charitable trusts and other bodies	Whereabouts of specifications and drawings if not filed in the Log Book
<p><u>FEB 2012:</u> QUINQUENNIAL INSPECTION CARRIED OUT BY R.W. PLATTS</p> <p><u>DEC 2012.</u> PULPIT FLOOR FOUND TO BE ROTTEN & IN A DANGEROUS STATE COMPLETE PULPIT REMOVED, FLOOR REPAIRED & PULPIT REINSTATED</p> <p><u>DEC 2012.</u> NEW CARPET AROUND PULPIT PURCHASED & FITTED. ALSO 2 PLATFORMS CARPETED TO MAKE FLAT AREA AROUND PULPIT.</p>		REF: 11/15/QI.01.	R.W. PLATTS.	£400		
			WORK CARRIED OUT BY A. MCCARTHY RINGMORE	£171.14		
			CARPET PURCHASED & FITTED BY A. MCCARTHY & P. ERRETT RINGMORE	£120.01		